

Clippard
 INSTRUMENT LABORATORY, Inc.
 Cincinnati, Ohio 45239
Minimatic[®]
 U.S. PAT. NO'S 3,766,935; 3,766,831 PAT'S PEND.

MADE IN U.S.A.

Pressure Reg. **R701**

Clippard
 INSTRUMENT LABORATORY, Inc.
 Cincinnati, Ohio 45239
Minimatic[®]
 U.S. PAT. NO'S 3,766,935; 3,766,831 PAT'S PEND.

MADE IN U.S.A.

Pressure Reg. **R701**



- WARNING -

FOR CONTINUED PROTECTION AGAINST FIRE HAZARD, REPLACE FUSES WITH SAME TYPE AND RATING ONLY.

DANGER
 HIGH VOLTAGE 1KV
 ELECTRIC SHOCK HAZARD
 REMOVE POWER BEFORE REPAIR OR ADJUSTMENT

FILLER PLUG & AIR VENT
 ABOVE -20°F. USE OIL. SPEC. MIL-H-5606
 BELOW -20°F. USE OIL SPEC. MIL-H-5606 MIXED WITH 26% NAPHTHA SPEC TT-N-95
CAUTION CLOSE AIR VENT WHEN NOT IN USE


CAUTION-HOT
 ALLOW TO COOL BEFORE REMOVAL
 HANDLE CAREFULLY- DELICATE LAMP FILAMENT



DANGER
 HIGH VOLTAGE 1KV
 ELECTRIC SHOCK HAZARD
 REMOVE POWER BEFORE REPAIR OR ADJUSTMENT

DANGER
 HIGH VOLTAGE 1KV
 ELECTRIC SHOCK HAZARD
 REMOVE POWER BEFORE REPAIR OR ADJUSTMENT

DANGER
 HIGH VOLTAGE 1KV
 ELECTRIC SHOCK HAZARD
 REMOVE POWER BEFORE REPAIR OR ADJUSTMENT



MOTOR-SYNCHRONOUS (DM)
 CONTINUOUS DUTY THERMAL PROTECTED
 1/35 H.P., 1 PH., 115 V.A.C., 50/60 HZ
 1500/1800 R.P.M. 75/ 65 AMPS
 CAP. 5 MFD 370 VAC
 INSULATION CLASS B
 PART NO. 252193



DANGER
 HIGH VOLTAGE 1KV
 ELECTRIC SHOCK HAZARD
 REMOVE POWER BEFORE REPAIR OR ADJUSTMENT

DANGER
 HIGH VOLTAGE 1KV
 ELECTRIC SHOCK HAZARD
 REMOVE POWER BEFORE REPAIR OR ADJUSTMENT

WARNING
 FOR-043 ANGLE GEARBOX ASSYS
 USE ONLY HYDRAULIC PUMPS THAT HAVE "O" RING TYPE GREASE RETENTION SPLINES (67WAF200 PUMP OR EQUIVALENT)

SS9013-1167

MOTOR-SYNCHRONOUS (DM)
 CONTINUOUS DUTY THERMAL PROTECTED
 1/35 H.P., 1 PH., 115 V.A.C., 50/60 HZ
 1500/1800 R.P.M. 75/ 65 AMPS
 CAP. 5 MFD 370 VAC
 INSULATION CLASS B
 PART NO. 252193



INTENSIFY

ACTIVATE

INTENSIFY

ACTIVATE

SLO-BLO

SLO-BLO



DANGER
 HIGH VOLTAGE 1KV
 ELECTRIC SHOCK HAZARD
 REMOVE POWER BEFORE REPAIR OR ADJUSTMENT